Pipeline Group Factual Report

ATTACHMENT 19

IMP Risk Model- Questions & Select Options for Defects

Carmichael, Mississippi DCA 08 MP 001

<u>Defects</u>	•
Welding records	
Strict welder qualification, complete records, 100% x-ray. Strict welder qualification, complete records, < 100% x-ray. Strict welder qualification, mostly complete records, < 100% x-ray Records incomplete. No records.	0 1 2 3 4 5
Pipe type	
Seamless. DSAW. Post 1970 ERW. Spiral weld. Pre 1970 ERW, lap weld, furnace butt weld or unknown.	0 1 2 3 4 5
Pipe manufacturer	
Known, highly reputable. Known, normally good quality. Known, quality sometimes questionable. Known, quality often a problem. Unknown.	0 1 2 3 4 5
Pipeline age	
5 years or less. 6 to 10 years. 11 to 20 years. 21 to 30 years. >30 years or unknown.	0 1 2 3 4 5
Normal operating pressure stress/SMYS	
< 20%. > 20% but < 40%. > 40% but < 50%. > 50% but < 60% > 60% but < 72%	0 1 2 3 4 5
Un-repaired defects	0
None. Some and in repair schedule. Some but not serious. Numerous. Unknown.	0 1 2 3 4 5

Pipe information Fully documented by mill certificates. 1 Documented with some mill certificates. 2 Manufacturing spec known but no mill certificates. 3 No specs or mill certificates but manufacturer known. 4 No information. 5 Backfill Excellent quality with documented construction and dig reports. 1 Good/excellent quality with no rocks. 2 Good quality with small rocks, no large rocks or small boulders. 3 Fair quality with some large rocks. 4 Poor quality or unknown. 5 History of defects related leaks/spills None in last 10 years. 0 One in last 10 years. 1 Two or more in last 10 years. 3 One in last two years. 4 One within last 12 months	
Fully documented by mill certificates. Documented with some mill certificates. Manufacturing spec known but no mill certificates. No specs or mill certificates but manufacturer known. No information. Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
Documented with some mill certificates. Manufacturing spec known but no mill certificates. No specs or mill certificates but manufacturer known. No information. Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
Manufacturing spec known but no mill certificates. No specs or mill certificates but manufacturer known. No information. Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
No specs or mill certificates but manufacturer known. No information. Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
No information. Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
Backfill Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. 5 History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years. One in last two years.	
Excellent quality with documented construction and dig reports. Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. 5 History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years. One in last two years.	
Good/excellent quality with no rocks. Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years. One in last two years.	
Good quality with small rocks, no large rocks or small boulders. Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years. One in last two years.	
Fair quality with some large rocks. Poor quality or unknown. History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years. 3 One in last two years.	
History of defects related leaks/spills None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
None in last 10 years. One in last 10 years. Two or more in last 10 years. One in last two years.	
One in last 10 years. Two or more in last 10 years. One in last two years. 4	
Two or more in last 10 years. One in last two years. 3	
One in last two years.	
The state of the s	
One within last 12 months	
Major line replacement history due to defects	
No replacements since start up	
No replacements since start-up.	
One replacement section within last 10 years.	
One replacement section within last 5 years.	
More than one replacement section within last 5 years.	
One or more replacement sections within last 12 months.	
Pressure test history	
Successful test within last 2 years. 0	
Successful test within last 5 years.	
Successful test within last 10years.	
Successful test within last 20 years.	
No test or records of test or test > 20 years ago.	
g	
Design engineering/construction records	
0	
Complete as-built drawings, material certificates and specifications.	
Mostly complete as-built drawings, material certificates and specifications.	
Complete as-built drawings, some certificates and specifications.	
Some as-built drawings, certificates and specifications.	
Incomplete. 5	

Q's and Select Box Options	Actual Values
MOP stress/SMYS	
	0
< 20%.	1
> 20% but < 40%.	2
> 40% but < 50%.	3
> 50% but < 60%	4
> 60% but < 72%	5
Anchor patterns near pipeline	
	0
Onshore - N/A.	1
Anchorling locations specied and strictly enforced.	2
Anchorling locations specied and usually enforced.	3
Anchoring locations generally specified.	4
Anchoring at any location.	5
Pressure cycles	
	0
No cycles, steady state flow.	1
< 7 cycles per week, small pressure differentials.	2
One or two cycles per day, large pressure differentials.	3
Frequent daily cycles, small pressure differentials.	4
Frequent daily cycles, large pressure differentials.	5
Pig run made for deformation anomaly detection	
	0
Made within last 12 months.	1
Made within last 3 years.	2
Made within last 5 years.	3
Made within last 10 years.	4
> 10 years or never made.	5

Pipe Segment: Hattiesburg to DemopolisSegment 1 367.39-371.63 4.24 Miles

4	Welding records		_ 3
,	vveiding records	Strict welder qualification, mostly complete records, < 10	▼
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	> 40% but < 50%.	▼ 3
6	Un-repaired defects	None.	→ 1
7	Pipe information	No specs or mill certificates but manufacturer known.	₩ 4
8	Backfill	Good quality with small rocks, no large rocks or small bou	▼ 3
9	History of defects related leaks/spills	None in last 10 years.	▼ 1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	→ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specific	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	₩ 5
14	Anchor patterns near pipeline	Onshore - N/A.	▼ 1
15	Pressure cycles	Frequent daily cycles, large pressure differentials.	▼ 5
16	Pig run made for deformation anomaly detection	> 10 years or never made.	5

Defects Total	est s	53
Defects Average		3.31
Defects Weighting Constant		0.348
Defects Threat Score	Artonia Produktori	1.15
Defects Percentage		66%

Pipe Segment: Hattiesburg to Demopolis Segment 2 378.49-381.19 2.69 Miles

1	Welding records	Strict welder qualification, mostly complete records, < 100^{d}	▼ , 3
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	> 20% but < 40%.	▼ 2
6	Un-repaired defects	None.	▼ 1
7	Pipe information	No specs or mill certificates but manufacturer known.	▼ 4
8	Backfill	Good quality with small rocks, no large rocks or small bould	▼ 3
9	History of defects related leaks/spills	None in last 10 years.	▼ 1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	▼ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specifica	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	▼ 5
14	Anchor patterns near pipeline	Onshore - N/A.	<u></u>
15	Pressure cycles	Frequent daily cycles, large pressure differentials.	▼ 5
16	Pig run made for deformation anomaly detection	> 10 years or never made.	▼ 5

Defects Total	52
Defects Average	3.25
Defects Weighting Constant	0.348
Defects Threat Score	1.13
Defects Percentage	65%

Pipe Segment: Hattiesburg to Demopolis Segment 3 387.48-390.77 3.29 Miles

1 Welding records	Strict welder qualification, mostly complete records, < 100	~
2 Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	T
3 Pipe manufacturer	Known, quality sometimes questionable.	~
4 Pipeline age	>30 years or unknown.	~
5 Normal operating pressure stress/SMYS	> 20% but < 40%.	•
6 Un-repaired defects	None.	<u>_</u>
7 Pipe information	No specs or mill certificates but manufacturer known.	•
8 Backfill	Good quality with small rocks, no large rocks or small bould	Ψ
9 History of defects related leaks/spills	None in last 10 years.	~
Major line replacement history due to defects	No replacements since start-up.	▼
1 Pressure test history	No test or records of test or test > 20 years ago.	•
2 Design engineering/construction records	Complete as-built drawings, some certificates and specifical	▼
3 MOP stress/SMYS	> 60% but < 72%	—
4 Anchor patterns near pipeline	Onshore - N/A.	₩
5 Pressure cycles	Frequent daily cycles, large pressure differentials.	•
6 Pig run made for deformation	> 10 years or never made.	

Defects Total	52
Defects Average	3.25
Defects Weighting Constant	0,348
Defects Threat Score	1.13
Defects Percentage	65%

Pipe Segment: Hattiesburg to Demopolis Segment 4 401.17-403.75 2.58 Miles

1	Welding records	Strict welder qualification, mostly complete records, < 100 ^d	<u>▼</u> . 3
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	> 20% but < 40%.	▼ 2
6	Un-repaired defects	None.	<u>→</u> 1
7	Pipe information	No specs or mill certificates but manufacturer known.	▼ 4
8	Backfill	Good quality with small rocks, no large rocks or small bould	₩ 3
9	History of defects related leaks/spills	None in last 10 years.	1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	▼ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specificat	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	▼ 5
14	Anchor patterns near pipeline	Onshore - N/A.	▼ 1
15	Pressure cycles	Frequent daily cycles, small pressure differentials.	▼ 4
16	Pig run made for deformation anomaly detection	> 10 years or never made.	y 5

Defects Total		51
Defects Average		3.19
Defects Weighting C	onstant	0.348
Defects Threat Score	9	1.11
Defects Percentage		64%

Pipe Segment: Hattiesburg to Demopolis Segment 5 411.64-422.33 10.58 Miles

1	Welding records	Strict welder qualification, mostly complete records, < 100	<u>▼</u> . 3
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	< 20%.	▼ 1
6	Un-repaired defects	None.	<u>▼</u> 1
7	Pipe information	No specs or mill certificates but manufacturer known.	▼ 4
8	Backfill	Good quality with small rocks, no large rocks or small bould	▼ 3
9	History of defects related leaks/spills	None in last 10 years.	▼ 1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	▼ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specifical	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	▼ 5
14	Anchor patterns near pipeline	Onshore - N/A.	▼ 1
15	Pressure cycles	Frequent daily cycles, small pressure differentials.	▼ 4
16	Pig run made for deformation anomaly detection	> 10 years or never made.	▼ 5

Defects Total	50
Defects Average	3.13
Defects Weighting Constant	0.348
Defects Threat Score	1.09
Defects Percentage	63%

Pipe Segment: Hattiesburg to Demopolis Segment 6 443.56-443.90 .34 Miles

1 Welding records	Strict welder qualification, mostly complete records, < 100	▼.
2 Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼
3 Pipe manufacturer	Known, quality sometimes questionable.	▼
4 Pipeline age	>30 years or unknown.	▼
5 Normal operating pressure stress/SMYS	> 20% but < 40%.	•
6 Un-repaired defects	None.	▼
7 Pipe information	No specs or mill certificates but manufacturer known.	▼
8 Backfill	Good quality with small rocks, no large rocks or small bould	▼
9 History of defects related leaks/spills	None in last 10 years.	▼
10 Major line replacement history due to defects	No replacements since start-up.	▼
11 Pressure test history	No test or records of test or test > 20 years ago.	▼
12 Design engineering/construction records	Complete as-built drawings, some certificates and specifical	
13 MOP stress/SMYS	> 60% but < 72%	▼
14 Anchor patterns near pipeline	Onshore - N/A.	▼
15 Pressure cycles	Frequent daily cycles, large pressure differentials.	▼
16 Pig run made for deformation anomaly detection	> 10 years or never made.	▼

Defects Total	52
Defects Average	3.25
Defects Weighting Constant	0.348
Defects Threat Score	1.13
Defects Percentage	65%

Pipe Segment: Hattiesburg to Demopolis Segment 7 448.9-459.87 10.97 Miles

1	Welding records	Strict welder qualification, mostly complete records, < 100	▼. 3
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	> 20% but < 40%.	▼ 2
6	Un-repaired defects	None.	▼ 1
7	Pipe information	No specs or mill certificates but manufacturer known.	▼ 4
8	Backfill	Good quality with small rocks, no large rocks or small bould	▼ 3
9	History of defects related leaks/spills	None in last 10 years.	▼ 1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	▼ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specifical	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	▼ 5
14	Anchor patterns near pipeline	Onshore - N/A.	▼ 1
15	Pressure cycles	Frequent daily cycles, large pressure differentials.	▼ 5
16	Pig run made for deformation anomaly detection	> 10 years or never made.	▼ 5

Defects Total	52
Defects Average	3.25
Defects Weighting Constant	0.348
Defects Threat Score	1.13
Defects Percentage	65%

Pipe Segment: Hattiesburg to Demopolis Segment 8 469.5-471.78 2.28 Miles

1	Welding records	Strict welder qualification, mostly complete records, < 100	▼. 3
2	Pipe type	Pre 1970 ERW, lap weld, furnace butt weld or unknown.	▼ 5
3	Pipe manufacturer	Known, quality sometimes questionable.	▼ 3
4	Pipeline age	>30 years or unknown.	▼ 5
5	Normal operating pressure stress/SMYS	> 20% but < 40%.	₹ 2
6	Un-repaired defects	None.	<u>▼</u> 1
7	Pipe information	No specs or mill certificates but manufacturer known.	▼ 4
8	Backfill	Good quality with small rocks, no large rocks or small bould	▼ 3
9	History of defects related leaks/spills	None in last 10 years.	▼ 1
10	Major line replacement history due to defects	No replacements since start-up.	▼ 1
11	Pressure test history	No test or records of test or test > 20 years ago.	▼ 5
12	Design engineering/construction records	Complete as-built drawings, some certificates and specifica	▼ 3
13	MOP stress/SMYS	> 60% but < 72%	▼ 5
14	Anchor patterns near pipeline	Onshore - N/A.	▼ 1
15	Pressure cycles	Frequent daily cycles, small pressure differentials.	▼ 4
16	Pig run made for deformation anomaly detection	> 10 years or never made.	▼ 5

Defects Total	51
Defects Average	3.19
Defects Weighting Constant	0,348
Defects Threat Score	1.11
Defects Percentage	64%

Pipe Segment: Hattiesburg to Demopolis Segment 9 482.4-487.84 5.44 Miles

Comments

Scoring Item Score
Threats

3rd Party Intervention

1 Pipeline in shared ROW	None.	•	
2 MOP stress/SMYS	> 60% but < 72%.	▼	
3 One call activity requiring Company response	10 to 25 call per month.	▼	
4 History of 3rd party intervention related leaks/spills	None in last 10 years.		
5 Patrol frequency	Once per week.	•	
6 Depth of cover/sand or grout bag cover	Less than 3 feet.	•	
7 Pipeline size	10.75-inch through 14-inch OD.	~	
8 Construction, development, dredging or farm activity on or near pipeline	Constantly/year round.	•	
9 ROW maintenance	Annual or as required (urban locations).	~	
Pipe manufacturer	Known, quality sometimes questionable.	•	
1 Normal operating pressure stress/SMYS	< 20%.	▼	
2 Pipeline signs and markers	Installed with annual inspection/repair/as required.	▼	
3 Foreign pipeline crossings	More than twenty.	▼	
4 Public awareness	Annual mailings or meetings.	•	
5 Operator present during 3rd party excavation	Never miss or N/A.	•	
6 Pipeline age	> 30 years or unknown.	▼	
7 Security for above ground facilities	Fenced, valves locked and chained.	•	

TPI Total	50
TPI Average	2.94
TPI Weighting Constant	0.183
TPI Threat Score	0.54
TPI Percentage	59%